



FOR THE PERFECT FIT...G-Force Helmet Fitment Guide

Carefully measure the circumference around drivers head. Start your measurement above the ears and roughly 1" above the eyebrows. After this measurement has been taken refer to the chart below for suggested fitment size for placing order. When you receive your helmet, please re-check for proper fitment by securely strapping helmet on. Attempt to roll helmet forward and off of your head. If helmet comes off, then a smaller helmet is needed. Assuring that the helmet fits the head properly provides maximum safety.

Measurement	Size	Metric
20-1/2"	6-1/2" (XX-Small)	52
20-7/8"	6-5/8" (X-Small)	53
21-1/4"	6-3/4" (X-Small)	54
21-5/8"	6-7/8" (Small)	55
22"	7 (Small)	56
22-3/8"	7-1/8" (Medium)	57
22-3/4"	7-1/4" (Medium)	58
23-1/8"	7-3/8" (Large)	59
23-1/2"	7-1/2" (Large)	60
23-7/8"	7-5/8" (X-Large)	61
24-1/4"	7-3/4" (X-Large)	62
24-3/4"	7-7/8" (XX-Large)	63
25-1/8"	8 (XX-Large)	64